## EXHIBIT 7

09-50026-mg Doc 13027-7 Filed 12/16/14 Entered 12/16/14 17:20:07 Exhibit 7

## TECHNICAL ASSISTANCE CENTER

## \*\*\*\* GM RESTRICTED \*\*\*\*

Case No: 06976834

VIN:

Privacy

Date Opened:

20031204

Model Year:

2003

AN

Date Closed:

02/03/2004

**Model Series:** 

\_\_\_\_

Dealer Code:

S121820

Mileage:

Division:

010210

Dealer Name:

Saturn Of Newburgh, West Nyack

Dealer State:

NY Saturn

Dealer Phone:

8453531919

SYMPTOM ABSTRACT---- STALL INT STALL NO COM ECM TCM

RESOLUTION ABSTRACT- CUSTOMER CONCERN NOT DUPLICATED - EMISSIONS

UCC CODE 1-----

UCC-1 DESCRIPTION--- Engine

UCC CODE 2-----

UCC-2 DESCRIPTION---

UCC CODE 3-----

UCC-3 DESCRIPTION---

12/04/2003 11:38:26 SBD Template - KICKIRILLO

vehicle came in for int stall coming to stop. tech can not com with ecm or tcm. Is using the candi module. advised tech to try tech2 and candi on another ion. if candi ok then try disconnecting tcm and see if he can com with ecm.

advised tech of current issues surrounding ign switch and heavy key chains.

12/04/2003 11:38:26 History - KICKIRILLO

02/03/2004 09:13:51 FRICKER - closing -

tech using red connector